

Community ALC models MUST BE updated to Firmware version 1.8.7.16 (or later) when running ArmoniaPlus v1.2.0 (or later).

The Firmware update process is automated within ArmoniaPlus v1.2.0

The first time ArmoniaPlus v1.2.0 tries to connect to Community ALC hardware via Ethernet, ArmoniaPlus will automatically identify ALC models with older firmware and will prompt the user to upgrade.

Simply click the "Upgrade" dialog and ArmoniaPlus will automatically download and install the latest firmware.

IMPORTANT!! After firmware installation, each ALC WILL AUTOMATICALLY REBOOT (shut down temporarily and restart). Take all necessary precautions.

The Firmware update will not affect any loudspeaker or user settings currently stored on ALC hardware.